Device Troubleshooting Guide



Parts of this document refer to inspection of the device's SIM card or SIM card slot. These can be prone to failure if not treated with care. Therefore, **only remove the SIM or SD card if requested to do so by the support team**OR if you think there is an issue, **please contact the support team before removing the SIM card or the SD card.**

DO NOT tamper with or open the device for any reason unless requested to do so by a member of the Tracplus team. Device batteries and electronics are not user-servicable.

Please contact support at support@tracplus.com or go to tracplus.com/contact-us for your regional support number.

SYMPTOM ISSUE REQUIRED ACTIONS → Start-up events showing in flight. ★ Visual diagnosis by TracPlus authorised person to inspect Battery failure battery, replace lower cover / battery assembly. Battery showing 0%. ★ Check for the latest firmware version and update. → Device tracks over cellular then doesn't switch back to cellular ★ Check reception and antenna placement. Intermittent Cell (LTE) tracking, i.e. it gets stuck on satellite ★ Check that the external antenna supports LTE (vs 3G), e.g. if tracking. device is an upgrade to a 3G device. ★ Visually inspect the SIM card tray for any damage and ensure that the SIM card is seated correctly in the tray. Ensure that the SIM card is not pushed through the SIM tray or has bent/ Tracks switch between cellular and damaged connectors as can happen when people try remove Intermittent Cell (3G) satellite frequently. them with a tool too aggressively. ★ Device will require repair from the manufacturer via a RMA process as it will need a replacement board. HARDWARE Progressively declining cellular ★ 3G networks are increasingly being shutdown and Declining cellular coverage and increase in number of performance will likely continue to decline. To continue to use performance on 3G cellular tracking of a RockAIR, it needs to be upgraded to a points being sent via satellite over RockAIRs built up areas. RockAIR LTE version. ★ Check SIM is an Emnify SIM and not Telstra SIM (all models after 2020 should be Emnify). Check SIM opening for damage to SIM card contacts. ★ Carefully inspect SIM card for damage (card may have been bent and no longer work). ★ Replace with a working SIM card and test. Device does not connect to cellular No cellular signal Confirm antenna supports LTE or 3G when using external network. antenna (e.g. device might be an upgrade). Confirm internal antenna is correct and not damaged. Confirm 3G coverage if testing a 3G device (e.g. LTE/5G is not compatible). Confirm cellular endpoint is rock7.inbound.tracplus.com. This can be updated by TracPlus support staff. → Delays in tracking reports appearing ★ Check mounting location of either the RockAIR or external (large gaps during a flight that then antenna if applicable. If either is behind the windshield of an backfill). aircraft that is IFR capable and has a heated windshield then this will create a condition where signal is extremely difficult to → Latencies of greater than two send/receive. minutes over satellite on TracPlus High latency satellite Cloud reports table. ★ Change mounting location to somewhere that has no heatedreporting Sequential reports over satellite with windshield element (i.e. top perspex window or external to the cockpit via externally mounted certified antenna). increasing latencies in order (i.e. 2 mins, 4 mins, 8 mins, 12 mins) as ★ If external antenna, confirm cable gauge is of suitable for the device queues reports and then length to receiver. eventually sends them at once. Tracking stops all of a sudden. Light Press the green button once and the light should turn solid Tracking suspended under the green button is flashing. again. Tracking should resume.

